

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	push\$3 near3 pool with weld\$4 with join\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 09:36
L2	20	push\$3 with (pool melt puddle) with weld\$4 with join\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 09:50
L3	1	("5591359").PN.	USPAT; USOCR	OR	OFF	2007/03/14 09:43
L4	1	3 and (push\$4 forc\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 09:44
L5	1	3 and (push\$4 forc\$4) with (laser beam)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 09:44
L6	36	(push\$3 with (pool melt\$2 puddle molten) with weld\$4) and (laser with weld\$4) not 2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 11:11
L7	31	((push\$3 forc\$4) near2 (pool melt\$2 puddle molten)) same weld\$4 same laser not 2 not 6	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 10:13
L8	16	6 and angle	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 11:14
L9	9003	laser with angle near2 inciden\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 11:15
L10	88	laser with angle near2 inciden\$3 with weld\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 11:15

EAST Search History

L11	45	laser with angle adj inciden\$3 with weld\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 11:15
L12	5	laser with angle adj inciden\$3 with weld\$3 with ("5" "20")	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:47
L13	40	11 not 12	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:44
L14	9	13 and angle with direction	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 11:59
L15	9	13 and angle with direction and angle	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 11:59
L17	0	(begin\$4 begun) near3 weld\$3 with larger near2 (work workpiece)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:33
L18	0	(begin\$4 begun) near3 weld\$3 with larger near2 sink	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:33
L19	0	(begin\$4 begun) near3 weld\$3 with larger with sink	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:33
L20	0	(begin\$4 begun) near3 weld\$3 with larg\$3 with sink	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:33
L21	0	(begin\$4 begun) near2 weld\$3 with heat near2 sink	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:34

EAST Search History

L22	1935	(begin\$4 begun) near2 weld\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:36
L23	96936	heat adj sink	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:34
L24	63	22 and 23	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:34
L25	8	22 same 23	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:34
L26	0	(begin\$4 begun) near2 weld\$3 with larger adj mass	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:36
L27	0	(initiat\$5 begin\$4 begun) near2 weld\$3 with larger adj mass	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:36
L28	1	(start\$3 initiat\$5 begin\$4 begun) - near2 weld\$3 with larger adj mass	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:38
L29	0	(start\$3 initiat\$5 begin\$4 begun) near2 weld\$3 with larger adj (work workpiece metal member)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:38
L30	5	(start\$3 initiat\$5 begin\$4 begun) near2 weld\$3 with (large\$ big\$4 great\$3) adj (work workpiece metal member)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:39
L31	6	13 and solid adj state	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:44

EAST Search History

L32	10	(laser with weld\$4) same (angle adj inciden\$3 with ("5" "20"))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/14 12:48
-----	----	---------------------------------------------------------------------	---------------------------------------------------------	----	----	------------------